

AIRFRAME LOG ENTRY FOR: NXXXXY

DATED: MAY 99, 2099; TACH TIME: 0000

PERFORM 100-HOUR AND 500-HOUR CLEANING, INSPECTION, AND LUBRICATION SERVICES OF THE FLAP TRANSMISSION; REFERENCING SECTION 5-50, ITEM# 4 FIGURE 2-20 [NOTES] PAGE 1D2, AND ITEM# 3 FIGURE 2-20 [SPECIAL INSTRUCTIONS] PAGE 1D6 OF THE PIPER TWIN COMANCHE SERVICE MANUAL 753-645, 9TH REVISION DATED OCTOBER 01, 1998, NO DISCREPANCIES FOUND. AN OPERATIONAL CHECK WAS PERFORMED AND FOUND TO BE SATISFACTORY. 0 - END - 0

_____ AP